

Map ID
Direction
Distance
Elevation

MAP FINDINGS

EDR ID Number
EPA ID Number

GL947
NNW
> 1
1.261 mi.
6660 ft.

**INTERSECTION - ACCIDENT
86TH ST AND BAY 40TH ST
BROOKLYN, NY**

**NY Spills S110488649
N/A**

Site 1 of 2 in cluster GL

**Relative:
Higher**

**Actual:
11 ft.**

SPILLS:

Name: INTERSECTION - ACCIDENT
Address: 86TH ST AND BAY 40TH ST
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 1002860 / 2010-06-30
Facility ID: 1002860
Facility Type: ER
DER Facility ID: 390942
Site ID: 436055
DEC Region: 2
Spill Cause: Traffic Accident
Spill Class: D4
SWIS: 2401
Spill Date: 2010-06-12
Investigator: RMPiPER
Referred To: Not reported
Reported to Dept: 2010-06-12
CID: Not reported
Water Affected: Not reported
Spill Source: Commercial Vehicle
Spill Notifier: Other
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False

Remediation Phase: 0
Date Entered In Computer: 2010-06-12
Spill Record Last Update: 2010-06-30
Spiller Name: Not reported
Spiller Company: NYC TRANSIT
Spiller Address: Not reported
Spiller Company: 999
Contact Name: JENNIFER WOUTENIN
DEC Memo: "DEC Piper received call off hours. Unable to reach caller Jenifer Wooten at office number provided to hotline. I received updat later that CO n Ed service boxes were affected and they will be sending out contractor. I asked Con Ed to have MTA call me. I recieved call from Jennifer Wooten She stated spill was cleaned by FDNY and contractor and that street was power washed. I recieved call from Con Ed that area was a mess. The street wasnlt cleaned and that speedy dry andd sand was all over. Con Ed stated they will clean street and their service boxes. I called Jen Wooten and explained that cleanup was not complete and that a third party should not be cleaning it. They should not rely on FDNY and that they had to take measures into their own hands in dealing with a spill. Spill cleaned by Son Ed. Follow up needed. DECPiper visited site. Residual speedy dry and sand were on street as well as pool of antifreeze on water. Emis 2218890 DECPiper received documetation of diposal. Case closed."

Remarks: "cleanup in progress - FDNY Hazmat on Scene @ 1917 - Bill Wainwright - Con Ed - 2 services boxes also affected by this spill - (box # 62507 and #61735(around the corner)- from NYC Transit accident"

All Materials:

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

Site ID: 436055
Operable Unit ID: 1186762
Operable Unit: 01
Material ID: 2181583
Material Code: 0008
Material Name: diesel
Case No.: Not reported
Material FA: Petroleum
Quantity: 100.00
Units: G
Recovered: Not reported
Oxygenate: Not reported